





Size & Type Guide










Cutting from the waffles.

Items are connected to base by supports. Generally support are cylindrical and conical. By using sharp knife cut single support and continue on next one until all become detached.



Then remove rest of support to create proper surface.



Holes and material removal

Resin is fragile. Extensive work or agressive attempt to remove material may lead to breakage. Please pay high attention when tooling. Do not overuse the cutting or drilling forces.



